



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management

Solid Waste Section

UNIT TYPE:

| | | | | | | | | | | | | |
|--------------|--|-----------------------|--|---------------|--|---------------------|--|---------|--|------|----------|------------------------|
| Lined MSWLF | | LCID | | YW | | Transfer | | Compost | | SLAS | X | COUNTY: Wake |
| Closed MSWLF | | HHW | | White goods | | Incin | | T&P | | FIRM | | PERMIT NO.: SLAS 92-01 |
| CDFL | | Tire T&P / Collection | | Tire Monofill | | Industrial Landfill | | DEMO | | SDTF | | FILE TYPE: COMPLIANCE |

Date of Site Inspection: 4/24/2012

Date of Last Inspection: 3/06/2012

FACILITY NAME AND ADDRESS:

Eastside Septic Cleaning Service
P.O. Box 365
Garner, NC 27529

GPS COORDINATES: N: 35.6491 W: -78.6008

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: B.C. Raynor
Telephone: (919) 772-6145
Email address:
Fax: (919) 773-1501

FACILITY CONTACT ADDRESS:

N/A

PARTICIPANTS:

Connie Wylie, Everett Coates

STATUS OF PERMIT:

Active

PURPOSE OF SITE VISIT:

Repermit

STATUS OF PAST NOTED VIOLATIONS:

N/A

OBSERVED VIOLATIONS

1. N/A

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may also be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

SEE BACK

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. Could not inspect entire site at this time due to locked gate, however site was last inspected on 3/06 with no significant problems noted. In regards to what could be inspected during this visit, no problems were noted.
2. Permit submittal is currently under review.
3. The required signs are posted and the access road is adequate.

Please contact me if you have any questions or concerns regarding this inspection report.



Connie S. Wylie
Regional Representative

Phone: (910) 433-3352

| | | | | | | | | |
|----------|--|-------|--|---------------|---|---------|--|-------------------------|
| Sent on: | | Email | | Hand delivery | X | US Mail | | Certified No. <u> </u> |
|----------|--|-------|--|---------------|---|---------|--|-------------------------|